


GUYMASTER Release Notes
For version 8.0.3 as of March 25, 2024

1. Fixed: The Importance factor value unintentionally modified, by the software, with the numerical value of the Seismic Importance Category. This value assignment happened only after the Seismic analysis run. The Importance Factor input field can be found on the first tab of the project Properties dialog box.



2. Fixed: The Antenna Rotation page presentation in the Draw Results module.